XX7	Δ1	I T3	D =	1501
Work	Org	ler I	1) 5	4564

December 11, 2009 3:32:14 PM



Page 1

Item ID: D206-781-023 Accept Setup Start **Revision ID:** Stop Item Name: Floor Protector (Passenger Cabin) Start Otv: 1.00 **Start Date:** 12/11/2009 **Cust Item ID: Required Date: 12/18/2009** Reg'd Oty: 1.00 **Customer:** Return 2009 / RA109109 / PAR09-037 Reference: Run Start Approvals: Process Plan: Date: Tooling: Date: Stop Date: 07.(2.11 SPC (Y/N): QC: Date: Sequence ID/ Reject Set Up/ Draw Draw Plan Reject Operation Accept Insp. Work Center ID Otv Code Number Stamp Description Run Hours Number Rev. Otv Draw Nbr **Revision Nbr** QC5- Inspect part completeness to step on W/O 100 0.00 0.00 QC Memo Orignal B50917 (replacement shippment part sent to customer) also cracked Quality Control Part is scrap & to be destroyed. * On Jop of englas Pur Live reference. 105.12.11. 110 -0.000.00 Packaging Memo Return the following items to stock. Packaging ***Have LL or Mel to make inventory adjustments*** 0.00 120 QC21-Final Inspection - Work Order Release

Quality Control

Memo

0.00

U (DO)-07

December 11, 2009 3:32:13 PM

Work Order ID: 54564

D206-781-023

Parent Item Name: Floor Protector (Passenger Cabin)

Comments.

Parent Item:



Start Date: 12/11/2009

Required Date: 12/18/2009

Start Oty 1 00

Paguired Oty: 1.00

Comments:								3	Start Qty:	1.00		Required C	2ty: 1.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaini Qty To P		Qty Issued	Date Issued	Status
D3934-041 Clip Assembly		Manufactured	No			110	Each	24.0000	2.0000	9	10/14	الع	
				<u>Warehou</u> <u>Locat</u> Main War	<u>ion</u>	<u>Loc (</u>	<u>Otv</u>	Loc Code					
					5 51172 52654		15 2 13		ļ				
				Main War ST13			9		į		2		
D3800-1-100 Hook and Loop Strip (1" Soi	1 11 11 11 11 11 11 11 11 11 11 11 11 1	Manufactured	No			110	f	40.8040	8.3330		1/12/	114	4
			<u>Warehou</u> <u>Locat</u> Main War	<u>ion</u>	<u>Loc (</u>	<u>Oty</u>	Loc Code					1	
				ST /	43558 52694		0.804 0.13 0.674						

Picklist Print

December 11, 2009 3:32:13 PM

Work Order ID: 54564 Parent Item:

D206-781-023

Parent Item Name: Floor Protector (Passenger Cabin)

Comments:



Start Date: 12/11/2009

Required Date: 12/18/2009

Page 2

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3800-3-100		Manufactured	No		**************************************	110	f	120.2580				
									J 3	20013	9/12/14-28	

Hook and Loop Strip (1" Hard)

Warehouse	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	80.914		
43560	0.13		_
44831	40.11		_
52695	40.674		_
Main Warehouse			
ST134	39.344		_
50541	39.344		_

AN525-10R6

Screw

Purchased

No

110

110.0000 4.0000 Each

Warehouse	Loc Oty	Loc Code
Location		
Main Warehouse		
ST	110	

110